



- 1 = WAVE ON SENSOR
- 2 = G 1/2" NUT, CRINKLE WASHER AND FLAT WASHER
- 3 = M10 STUDDING X 50MM LENGTH
- 4 = M10 NUT AND SQUARE WASHER
- 5 = OUTLET ASSEMBLY